

Horizon



Alimentação Vac/Hz	Potência HP	Rot. motor RPM	Consumo A	Capacitor mF	Velocidade do pino de acionamento (m/min)			Tempo de abertura considerando o curso do pino (1200)		
					Passo 45	Passo 60	Passo 100	Passo 45	Passo 60	Passo 100
110/60	1/4	1.740	2,4	25	4,9	6,5	10,8	14	11	6
110/60	1/4	1.100	2,4	25	-	4,1	-	-	17	-
220/60	1/4	1.740	1,2	10	4,9	6,5	10,8	14	11	6
220T/60	1/4	1.740	1,15	-	4,9	6,5	10,8	14	11	6

